

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

10

Michael O. Leavitt Governor Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801

Salt Lake City, Utah 84114-5801 801-538-5340

801-359-3940 (Fax)

801-538-7223 (TDD)

Partial: XXX Complete: Exploration: Inspection Date & Time: 9/17/99 / 8:30A.M.-11:00A.M.

Date of Last Inspection: 8/20/99

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]		[XX]	[]
2.	SIGNS AND MARKERS	[XX]	Ħ	[XX]	Ħ
3.	TOPSOIL	[]	Ħ	[]	Ħ
4.	HYDROLOGIC BALANCE:	44			-
a.	DIVERSIONS	[XX]	f 1	[]	[]
b.	SEDIMENT PONDS AND IMPOUNDMENTS	<u>ixxi</u>	īi	\overrightarrow{XX}	
c.	OTHER SEDIMENT CONTROL MEASURES		Π	ii ii	
d.	WATER MONITORING	Π	Π	ī	īī
e.	EFFLUENT LIMITATIONS	ii .	П	īī	ī
5.	EXPLOSIVES	īī	П		\Box
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	ī	$\overline{[XX]}$		፲
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[XX]		\Box	
8.	NONCOAL WASTE	[XX] [XX]	\Box	\Box	
9.	PROTECTION OF FISH, WILDLIFE AND				
	RELATED ENVIRONMENTAL VALUES	Ц	\Box	П	\Box
10.	SLIDES AND OTHER DAMAGE		$\overline{[XX]}$	\Box	\Box
11.	CONTEMPORANEOUS RECLAMATION	\Box	Ш	Ξ	\Box
12.	BACKFILLING AND GRADING	\Box	[XX]	ĹΪ	П
13.	REVEGETATION	\Box	Ш	Π	\Box
14.	SUBSIDENCE CONTROL		\Box	Π	\Box
15.	CESSATION OF OPERATIONS	\Box	[XX]	\Box	\Box
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[XX]	\Box	\Box	\Box
b.		[XX]	Ш	\Box	\Box
17.	OTHER TRANSPORTATION FACILITIES	\Box	\Box	\Box	\Box
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[XX]	Ш	\Box	\Box
19.	AVS CHECK (4th Quarter-April, May, June) (date)			\Box	
20.	AIR QUALITY PERMIT	[XX]	\Box	[XX]	\Box
21.	BONDING & INSURANCE	[]	ſĪ	[]	F 1

INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>2</u>

PERMIT NUMBER: ACT/007/038

DATE OF INSPECTION: 9/17/99

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permittee has the following amendments under review within the Division:

- a) ACT/007/038-98G, Willow Creek As-Builts. This submittal is in the UDNR/OGM's court; a deficiency response is pending.
- b) ACT/007/038-99E, BTU Resource Recovery from the School House Canyon Refuse facility; UDNR/OGM response is pending.
- c) ACT/007/038-99F, Minor Coal Exploration application received on 9/16/99; UDNR/OGM review is pending.

2. SIGNS AND MARKERS

The permittee was observed changing permittee identification signs at the access entrance to the Willow Creek Preparation Plant. Effective June 30, Cyprus Plateau Mining Corporation has now become Plateau Mining Corporation. RAG American Coal Holding, Inc., is the parent company.

4b. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The permittee is in the process of cleaning sediment pond 011A. Mr. Pappas has postponed this project as long as possible, hoping that the sediment in the pond would have the opportunity to dry. Recent storms have prevented this from occurring. The sediment pond clean out material is being disposed of on the School House Canyon waste rock facility.

The pond will require re-certification by a registered professional engineer to determine that same has been maintained according to the original design approved in the MRP; (R645-301-514.312).

11. RECLAMATION

The permittee has reclaimed the drill site and the access road which were developed for exploration and mine atmosphere monitoring in Dinosaur Canyon. A track hoe was observed at the junction of the Dinosaur Canyon road and another hole access road which was drilled during the fire evaluation period (mid-Eagle/Dinosaur Canyons).

The contractor who is performing this work was working on pond 011A this day, as the hoe mentioned above was broken down. It is believed that the seeding still needs to be performed.

20. AIR QUALITY PERMIT

The School House Canyon refuse facility access road had been recently watered. A waste rock truck was operating during today's inspection.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Johnny Pappas (Plateau) Henry Austin (OSM)
Given to: Pam Grubaugh-Littig (DOGM)
Filed to: Price Field Office

Date: September 17, 1999

#46

Inspector's Signature:

Peter Hess